






PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	January 23, 2024
Inspector Name	Connor Gregory	Time of Inspection	04:37 PM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	John Sal and coogan are pulling cat 6 cable all over for lighting control devices such as switches relays and occ sensors	
Was work completed?	Satisfactory	Nick and Justin are mounting boxes and cutting in cables in preparation of lighting control devices	
Was work completed?	Satisfactory	This ran some conduits between the second and first floor	
Was work completed?	N/A		-
Was work completed?	N/A		-