




# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Positive Electric Co.	<b>Type of Inspection:</b>	Job Progress Inspection
<b>Project</b>	Summit Fire House	<b>Date of Inspection</b>	January 24, 2024
<b>Inspector Name</b>	Connor Gregory	<b>Time of Inspection</b>	11:40 AM

## INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	Monday 1/22 Conduits began to run out of main electrical room first floor	
Was work completed?	Satisfactory	Monday 1/22 John coogan and Sal continued running the emergency circuit for em lights and exit signs	-
Was work completed?	Satisfactory	Monday 1/22 Justin nick and coogan began prepping occ sensor boxes and running cat 6 cable for control devices	-
Was work completed?	N/A		-
Was work completed?	N/A		-