







PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	January 31, 2024
Inspector Name	Connor Gregory	Time of Inspection	12:37 PM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	Tuesday 1/30 Ken finished the conduit run for the scba panel	
Was work completed?	Satisfactory	Justin plugging away on second floor outlets	
Was work completed?	Satisfactory	Nick installed the outside terrace fixtures OD-9	

<p>Was work completed?</p>	<p>Satisfactory</p>	<p>Tomas finished cutting in the added quad outlets and data drops</p>	
<p>Was work completed?</p>	<p>Satisfactory</p>	<p>John and Sal finished running the conduit for all outlets and equipment in mezzanine mechanical room</p>	