







# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Positive Electric Co.	<b>Type of Inspection:</b>	Job Progress Inspection
<b>Project</b>	Summit Fire House	<b>Date of Inspection</b>	January 31, 2024
<b>Inspector Name</b>	Connor Gregory	<b>Time of Inspection</b>	04:08 PM

## INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	1/31 Ken installed the final re-7 fixture on the second floor, also fixed a missed outdoor outlet box	
Was work completed?	Satisfactory	1/31 Nick installed the j box for the light and a j box for the exhaust fan in the patio storage closet	
Was work completed?	Satisfactory	1/31 Tomas finished cutting sheet rock and installing old work boxes for the added office outlets on the second floor.	

<p>Was work completed?</p>	<p>Satisfactory</p>	<p>1/31 Justin is still plugging away on second floor</p>	
<p>Was work completed?</p>	<p>Satisfactory</p>	<p>1/31 Lights and exit signs being piped in mezzanine</p>	