








# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Positive Electric Co.	<b>Type of Inspection:</b>	Job Progress Inspection
<b>Project</b>	Summit Fire House	<b>Date of Inspection</b>	February 05, 2024
<b>Inspector Name</b>	Connor Gregory	<b>Time of Inspection</b>	02:55 PM

## INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	Coogan and Sal finished the control portion of the split units	
Was work completed?	Satisfactory	Tomas did some outlets and fixed illegal pvc in second floor ceilings	
Was work completed?	Satisfactory	Justin started making cat 6 heads for lighting control devices on second floor	
Was work completed?	Satisfactory	Nick is taking care of miscellaneous light fixtures on second floor such as the patio storage closet light	

<p>Was work completed?</p>	<p>Satisfactory</p>	<p>Above ceiling inspection for toilet 214 and 215 on second floor</p>	
----------------------------	---------------------	--	---