







# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Positive Electric Co.	<b>Type of Inspection:</b>	Job Progress Inspection
<b>Project</b>	Summit Fire House	<b>Date of Inspection</b>	February 06, 2024
<b>Inspector Name</b>	Connor Gregory	<b>Time of Inspection</b>	03:03 PM

## INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	Ken and nick installed one and a half pd-72 in the day room	
Was work completed?	Satisfactory	Justin still moving with cat6 heads for light control	
Was work completed?	Satisfactory	Sal finished pipe in mezzanine training room for lights	

<p>Was work completed?</p>	<p>Satisfactory</p>	<p>Tomas did some miscellaneous outlets such as outside outlets and pulled a jumper cable from one to another that was missing</p>	
<p>Was work completed?</p>	<p>Satisfactory</p>	<p>Coogan cleaned up some of the previous electricians work all over the second floor by adding legal supports</p>	