







PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	February 07, 2024
Inspector Name	Connor Gregory	Time of Inspection	04:03 PM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	7/8 of the conduits that leave panel L2 are stubbed out into the bay by Ken and coogan	
Was work completed?	Satisfactory	Another decorative fixture put up today by Sal and nick	
Was work completed?	Satisfactory	Jared jake and Justin doing lighting control on second floor	

<p>Was work completed?</p>	<p>Satisfactory</p>	<p>Another pic of lighting control</p>	
<p>Was work completed?</p>	<p>Satisfactory</p>	<p>Me and kris have one more 4" pipe to complete the service/generator feed underground</p>	