







# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Positive Electric Co.	<b>Type of Inspection:</b>	Job Progress Inspection
<b>Project</b>	Summit Fire House	<b>Date of Inspection</b>	February 09, 2024
<b>Inspector Name</b>	Connor Gregory	<b>Time of Inspection</b>	03:43 PM

## INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	Cad welding began and 2 generator conduits + site light conduit stubbed up	
Was work completed?	Satisfactory	Ken and coogan added lower racks and began the lower conduits into the box from first floor electric room	
Was work completed?	Satisfactory	Nick hanging the pd-12 fixtures above the kitchen island	

Was work completed?	Satisfactory	Jared Jake Justin and Kris banging out the lighting controls and devices on 2F	
Was work completed?	Satisfactory		-