







PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	February 12, 2024
Inspector Name	Connor Gregory	Time of Inspection	03:12 PM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	Grounding counterpoise ring for service complete	
Was work completed?	Satisfactory	14 type wa-1 fixtures are up by nick, he also started the exit signs	
Was work completed?	Satisfactory	Exit signs going up on second floor	

Was work completed?	Satisfactory	Jared Jake and Justin still installing lighting control Devices	
Was work completed?	Satisfactory	Kris began fire stopping the fire rated walls on the second floor	-