






PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	February 15, 2024
Inspector Name	Connor Gregory	Time of Inspection	03:25 PM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	2/14 Jared Jake Justin doin lighting control on second floor	
Was work completed?	Satisfactory	2/14 Kris doing fire caulk on second floor	
Was work completed?	Satisfactory	2/14 Sal and nick finished exit signs on second floor	

Was work completed?	Satisfactory	Ken and coogan doing more pipe for first floor branch circuits in app bay	
Was work completed?	Satisfactory		-