





PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	February 23, 2024
Inspector Name	Connor Gregory	Time of Inspection	07:29 AM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	2/22 Room 107 high hats in and wire pulled, half of the high hats are wired and supported.	
Was work completed?	Satisfactory	2/22 All sub panel feeders from the load side of the MDS are pulled, and termination has begun.	
Was work completed?	N/A		-
Was work completed?	N/A		-
Was work completed?	N/A		-