







PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	February 29, 2024
Inspector Name	Connor Gregory	Time of Inspection	04:46 PM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	Ken and Justin started megging the sub panel feeders and helping me mount the outdoor MTS	
Was work completed?	Satisfactory	Jake starting the cut in panel ML6	
Was work completed?	Satisfactory	Kris and nick running the 2" comm conduit from the utility pole	

<p>Was work completed?</p>	<p>Satisfactory</p>	<p>Coogan ran pvc for site lights</p>	
<p>Was work completed?</p>	<p>Satisfactory</p>	<p>Sal and Tomas finished running conduit and pulling wire and devicing the mezz mechanical room</p>	