







PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	March 06, 2024
Inspector Name	Connor Gregory	Time of Inspection	05:27 AM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	Jake and coogan are running conduit in the apparatus bay for east garage doors, destrat fans and east exterior lights	
Was work completed?	Satisfactory	Steve and Tomas are terminating the main electric room	
Was work completed?	Satisfactory	Sal working on first floor lights	

<p>Was work completed?</p>	<p>Satisfactory</p>	<p>Nick and kris finished running the 4" and 2" comm conduits (for now) and got then disconnect up for ahu-1 and wired the unit</p>	
<p>Was work completed?</p>	<p>Satisfactory</p>	<p>Lie and Justin running conduit in the mezz training room for local home runs and branch ckts</p>	