







PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	March 07, 2024
Inspector Name	Connor Gregory	Time of Inspection	07:16 AM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	3/6 Jake and coogan piping in apparatus bay for garage door motors	
Was work completed?	Satisfactory	3/6 Steve and Tomas are terminating panels in main electric room	
Was work completed?	Satisfactory	3/6 Nick and kris are hanging track lights on first floor	

<p>Was work completed?</p>	<p>Satisfactory</p>	<p>3/6 Sal is wiring exit lights and high hats on first floor</p>	
<p>Was work completed?</p>	<p>Satisfactory</p>	<p>3/6 Charlie and Justin are running conduit in mezzanine training area for branch circuits in the area</p>	