







PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	March 15, 2024
Inspector Name	Connor Gregory	Time of Inspection	05:32 AM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	3/13 All hands on deck to pull service feeders (Me kris Kaseem leaf John and coogan)	
Was work completed?	Satisfactory	3/13 more service wire	
Was work completed?	Satisfactory	3/13 Charlie terminating ATS feeders	

<p>Was work completed?</p>	<p>Satisfactory</p>	<p>3/13 Jake running conduit in apparatus bay for lights</p>	
<p>Was work completed?</p>	<p>Satisfactory</p>	<p>3/13 Nick pulling cable on first floor for watch room lights</p>	