







PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	March 15, 2024
Inspector Name	Connor Gregory	Time of Inspection	05:32 AM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	3/14 Charlie and Tomas landing service in MDS	
Was work completed?	Satisfactory	3/14 Steve and Justin landing service feeders in cold sequence disconnect	
Was work completed?	Satisfactory	3/14 Jared and Adam landing wires in service transformer	

<p>Was work completed?</p>	<p>Satisfactory</p>	<p>3/14 John and leaf running life safety conduit in app bay. Jake and coogan continued conduit for lights in app bay as well.</p>	
<p>Was work completed?</p>	<p>Satisfactory</p>	<p>3/14 Sal kris and Kaseem pulling branch circuit wires in mezz for power and equipment, also installing devices and disconnect switches.</p>	