







# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Positive Electric Co.	<b>Type of Inspection:</b>	Job Progress Inspection
<b>Project</b>	Summit Fire House	<b>Date of Inspection</b>	March 28, 2024
<b>Inspector Name</b>	Connor Gregory	<b>Time of Inspection</b>	05:39 AM

## INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	3/27 Charlie and Tomas continuing conduit in electrical room on first floor	
Was work completed?	Satisfactory	3/27 Sal and Steve getting rods down and strut hung for lights in locker room on first floor	
Was work completed?	Satisfactory	3/27 Nick and kris finished the 4" conduit for fiber	

Was work completed?	Satisfactory	3/27 Jake and coogan pulled mc from low ceiling to high ceiling in historical room and watch room	
Was work completed?	Satisfactory	3/27 Justin and leaf did some miscellaneous mc pulls on second floor for exterior lights on terrace and lighting control devices	-