







PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	April 08, 2024
Inspector Name	Connor Gregory	Time of Inspection	05:42 AM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	4/3 Jake and leaf buttoning up loose ends in watch room ceiling with power and lighting	
Was work completed?	Satisfactory	4/3 Adam and Justin installing fixtures and wiring in locker room on first floor	
Was work completed?	Satisfactory	4/3 Sal running mc jumpers on first floor	

<p>Was work completed?</p>	<p>Satisfactory</p>	<p>4/3 Ken and coogan running conduit on first floor for emergency lighting</p>	
<p>Was work completed?</p>	<p>Satisfactory</p>	<p>4/3 Nick and kris running conduit in stairs for lights Charlie and Tomas are pulling mezzanine home runs</p>	