







# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Positive Electric Co.	<b>Type of Inspection:</b>	Job Progress Inspection
<b>Project</b>	Summit Fire House	<b>Date of Inspection</b>	April 08, 2024
<b>Inspector Name</b>	Connor Gregory	<b>Time of Inspection</b>	01:38 PM

## INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	4/5 Nick and kris continuing stairwell light conduit	
Was work completed?	Satisfactory	4/5 Ken installed a big light in first floor bathroom	
Was work completed?	Satisfactory	4/5 Sal installed a light in the janitor closet and pulled some mc branch circuits	

<p>Was work completed?</p>	<p>Satisfactory</p>	<p>4/5 Jake and leaf and Kaseem are installing lighting controls and wire for first floor lights</p>	
<p>Was work completed?</p>	<p>Satisfactory</p>	<p>4/5 Charlie and Tomas are pulling wire for first floor and mezz branch circuits</p>	