







PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	April 09, 2024
Inspector Name	Connor Gregory	Time of Inspection	05:37 AM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	4/8 Charlie and Tomas pulling first floor home runs	
Was work completed?	Satisfactory	4/8 Kaseem working on first floor lighting control	
Was work completed?	Satisfactory	4/8 Adam and Justin running app bay conduit for lighting and controls	

<p>Was work completed?</p>	<p>Satisfactory</p>	<p>4/8 Nick and kris are installing stairwell lighting and associated conduit and wire</p>	
<p>Was work completed?</p>	<p>Satisfactory</p>	<p>4/8 Leaf and Sal did first floor branch circuit cables and mounted a heater in the stairs</p>	