








PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	April 11, 2024
Inspector Name	Connor Gregory	Time of Inspection	06:05 AM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	4/10 Justin ran conduit in the app bay for lights	
Was work completed?	Satisfactory	4/10 Leaf running conduit in water room for power and lights	
Was work completed?	Satisfactory	4/10 Charlie and Tomas pulling first floor home runs	
Was work completed?	Satisfactory	4/10 Nick and kris running conduit in stair 3 for lights	

<p>Was work completed?</p>	<p>Satisfactory</p>	<p>4/10 Sal putting up lights and outlets on first floor</p>	
----------------------------	---------------------	--	---