








PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| | | | |
|-----------------------|-----------------------|----------------------------|-------------------------|
| Company | Positive Electric Co. | Type of Inspection: | Job Progress Inspection |
| Project | Summit Fire House | Date of Inspection | April 12, 2024 |
| Inspector Name | Connor Gregory | Time of Inspection | 05:50 AM |

INSPECTION ITEMS

| Item | | Comment | Photo |
|----------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|-------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Is a safety program in place? | Satisfactory | 4/10 Justin ran pipe for lights in app bay |  |
| Are safety tailgate meetings being done? | Satisfactory | 4/10 Leaf running conduit in water room |  |
| Click "Satisfactory" and enter if there is rainfall in the comments section below. If there is rainfall, please note the amount in inches below as well. | Satisfactory | 4/10 Charlie and Tomas pulling first floor home runs |  |
| Test 1 | Satisfactory | 4/10 Nick and kris running conduit in stairway 3 for lights |  |

| | | | |
|-------------------------|--------------|----------------------------------------------------|-------------------------------------------------------------------------------------|
| Test 2 | Satisfactory | 4/10 Sal installing first floor lights and outlets |  |
| This is a test question | N/A | | - |