








PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	April 12, 2024
Inspector Name	Connor Gregory	Time of Inspection	05:50 AM

INSPECTION ITEMS

Item		Comment	Photo
Is a safety program in place?	Satisfactory	4/11 Sal installing and wiring lights in mezz training room	
Are safety tailgate meetings being done?	Satisfactory	4/11 Justin running conduit in scuba room for lights and power	
Click "Satisfactory" and enter if there is rainfall in the comments section below. If there is rainfall, please note the amount in inches below as well.	Satisfactory	4/11 Charlie and Tomas installing a branch circuit conduit in app bay for first floor home runs and began the generator conduits that enter the building	
Test 1	Satisfactory	4/11 Leaf running conduit in water room	
Test 2	Satisfactory	4/11 Nick and kris running conduit in stair 3 for lights	
This is a test question	N/A		-