








PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	April 15, 2024
Inspector Name	Connor Gregory	Time of Inspection	05:36 AM

INSPECTION ITEMS

Item		Comment	Photo
Is a safety program in place?	Satisfactory	4/12 Charlie and Tomas got the conduits for the generators up and thru the building	
Are safety tailgate meetings being done?	Satisfactory	4/12 Ken and Justin running conduit for lights and controls in app bay	
Click "Satisfactory" and enter if there is rainfall in the comments section below. If there is rainfall, please note the amount in inches below as well.	Satisfactory	4/12 Nick and kris running conduit and hanging lights in stair 3	
Test 1	Satisfactory	4/12 Leaf running conduit in water room for power and lights	
Test 2	Satisfactory	4/12 Sal hanging and wiring lights in mezz training room	
This is a test question	N/A		-