








PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	April 16, 2024
Inspector Name	Connor Gregory	Time of Inspection	05:37 AM

INSPECTION ITEMS

Item		Comment	Photo
Is a safety program in place?	Satisfactory	4/15 Sal installing and wiring mezzanine training room lights	
Are safety tailgate meetings being done?	Satisfactory	4/15 Adam and Justin piping occ sensors in app bay	
Click "Satisfactory" and enter if there is rainfall in the comments section below. If there is rainfall, please note the amount in inches below as well.	Satisfactory	4/15 Nick and kris piping power and mechanical in hose tower stair	
Test 1	Satisfactory	4/15 Charlie and Tomas piping 4":conduit for generator feed	
Test 2	Satisfactory	4/15 Jake and leaf piping to lights in app bay	
This is a test question	N/A		-