



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

COMPANY	ABC & Co.	PROJECT	Project 2 Test
Date Of Incident	May 24, 2018	Time Of Incident	01:03 PM
Inspector	user@gmail.com		

QUESTIONS:

Question # 1. Lorem Ipsum is simply dummy text of the printing and typesetting industry.xxxxx

satisfactory

Question # 2. Fall Protection

satisfactory

Question # 3. Trenching & excavation work being done safely

na

Question # 4. Trenching & excavation work being done safely

na

Question # 5. Scissor lifts / elevated platforms are being used safely

na

Question # 6. Tools & equipment are being used safely

na

Question # 7. Personal Protective Equipment is being worn as required

na

Question # 8. Are Safety Nets set up safely

Answer : **Unsatisfactory**