

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

COMPANY	ABC & Co.	PROJECT	Project 2 Test
Date Of Incident	June 01, 2018	Time Of Incident	08:06 PM
Inspector	user@gmail.com		
QUESTIONS:			
QUEUTIONO.			
Question # 1. Safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)			
satisfactory			

Question # 2. Good housekeeping being maintained

satisfactory

Question # 3. Fall Protection in place where required

satisfactory

Question # 4. Confined Space procedures being followed

satisfactory

Question # 5. Trenching & excavation work being done safely

satisfactory

Question # 6. Scaffolding safety procedures are being followed

Answer: Unsatisfactory