



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| | | | |
|-------------------------|------------------|-------------------------|----------------|
| COMPANY | ABC & Co. | PROJECT | Project 2 Test |
| Date Of Incident | January 01, 1970 | Time Of Incident | 02:00 AM |
| Inspector | user@gmail.com | | |

QUESTIONS:

Question # 1. Lorem Ipsum is simply dummy text of the printing and typesetting industry.xxxxx

satisfactory

Question # 2. Fall Protection

satisfactory

Question # 3. Trenching & excavation work being done safely

satisfactory

Question # 4. Trenching & excavation work being done safely

satisfactory

Question # 5. Scissor lifts / elevated platforms are being used safely

satisfactory

Question # 6. Tools & equipment are being used safely

satisfactory

Question # 7. Personal Protective Equipment is being worn as required

satisfactory

Question # 8. Are Safety Nets set up safely

satisfactory