



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	ABC & Co.	<b>Type of Inspection:</b>	Roofing Inspection
<b>Project</b>	Project 2 Test	<b>Date Of Incident</b>	June 21, 2018
<b>Inspector Name</b>	user@gmail.com	<b>Time Of Incident</b>	11:48 AM

## INSPECTION ITEMS

Item		Comment
Fall Protection	Satisfactory	
Trenching & excavation work being done safely	Satisfactory	
Trenching & excavation work being done safely	Satisfactory	
Scissor lifts / elevated platforms are being used safely	Satisfactory	
Tools & equipment are being used safely	Satisfactory	
Personal Protective Equipment is being worn as required	Satisfactory	
Are Safety Nets set up safely	Satisfactory	