

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| Company | ABC & Co. | Type of Inspection: | Framing Inspection |
|----------------|----------------|---------------------|--------------------|
| Project | Project 2 Test | Date Of Incident | June 26, 2018 |
| Inspector Name | user@gmail.com | Time Of Incident | 07:48 PM |

INSPECTION ITEMS

| Item | | Comment |
|---|--------------|---------|
| Fall Protection | Satisfactory | |
| Trenching & excavation work being done safely | Satisfactory | |
| Trenching & excavation work being done safely | Satisfactory | |
| Scissor lifts / elevated platforms are being used safely | Satisfactory | |
| Tools & equipment are being used safely | Satisfactory | |
| Personal Protective Equipment is being worn as required | Satisfactory | |
| Are Safety Nets set up safely | Satisfactory | |
| Lorem Ipsum is simply dummy text of the printing. | Satisfactory | |
| Lorem Ipsum is simply dummy text of the printing and typesetting industry.123 | Satisfactory | |