



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

|                       |                |                            |                    |
|-----------------------|----------------|----------------------------|--------------------|
| <b>Company</b>        | ABC & Co.      | <b>Type of Inspection:</b> | Framing Inspection |
| <b>Project</b>        | Project 2 Test | <b>Date Of Incident</b>    | June 26, 2018      |
| <b>Inspector Name</b> | user@gmail.com | <b>Time Of Incident</b>    | 07:48 PM           |

## INSPECTION ITEMS

| Item  |              | Comment |
|---|--------------|---------|
| Fall Protection   | Satisfactory |         |
| Trenching & excavation work being done safely                                 | Satisfactory |         |
| Trenching & excavation work being done safely                                 | Satisfactory |         |
| Scissor lifts / elevated platforms are being used safely                      | Satisfactory |         |
| Tools & equipment are being used safely                                       | Satisfactory |         |
| Personal Protective Equipment is being worn as required                       | Satisfactory |         |
| Are Safety Nets set up safely   | Satisfactory |         |
| Lorem Ipsum is simply dummy text of the printing.                             | Satisfactory |         |
| Lorem Ipsum is simply dummy text of the printing and typesetting industry.123 | Satisfactory |         |