



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	ABC & Co.	<b>Type of Inspection:</b>	Framing Inspection
<b>Project</b>	Project 2 Test	<b>Date Of Incident</b>	June 26, 2018
<b>Inspector Name</b>	user@gmail.com	<b>Time Of Incident</b>	07:48 PM

## INSPECTION ITEMS

Item		Comment
Fall Protection	Satisfactory	
Trenching & excavation work being done safely	Satisfactory	
Trenching & excavation work being done safely	Satisfactory	
Scissor lifts / elevated platforms are being used safely	Satisfactory	
Tools & equipment are being used safely	Satisfactory	
Personal Protective Equipment is being worn as required	Satisfactory	
Are Safety Nets set up safely	Satisfactory	
Lorem Ipsum is simply dummy text of the printing.	Satisfactory	
Lorem Ipsum is simply dummy text of the printing and typesetting industry.123	Satisfactory	