



PROJECT INSPECTION


Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	ABC & Co.	Type of Inspection:	Roofing Inspection
Project	Project 2 Test	Date Of Incident	June 27, 2018
Inspector Name	user@gmail.com	Time Of Incident	10:06 PM

INSPECTION ITEMS

Item		Comment
Fall Protection	Unsatisfactory	
Trenching & excavation work being done safely	Satisfactory	
Trenching & excavation work being done safely	Unsatisfactory	z
Scissor lifts / elevated platforms are being used safely	Unsatisfactory	
Tools & equipment are being used safely	Unsatisfactory	
Personal Protective Equipment is being worn as required	Unsatisfactory	
Are Safety Nets set up safely	Unsatisfactory	

UNSATISFACTORY ITEMS

Photo	Comment	Corrective Action
-		
		
-		
-		

-		
-		