



PROJECT INSPECTION


Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com


Company	ABC & Co.	Type of Inspection:	Roofing Inspection
Project	Project 2 Test	Date Of Incident	June 29, 2018
Inspector Name	user@gmail.com	Time Of Incident	06:02 PM

INSPECTION ITEMS

Item		Comment
Fall Protection	Unsatisfactory	
Trenching & excavation work being done safely	Unsatisfactory	
Trenching & excavation work being done safely	Na	
Scissor lifts / elevated platforms are being used safely	Satisfactory	
Tools & equipment are being used safely	Satisfactory	
Personal Protective Equipment is being worn as required	Satisfactory	
Are Safety Nets set up safely	Satisfactory	

UNSATISFACTORY ITEMS

Photo	Comment	Corrective Action
	Hujjjj	



Bhhhh