

# **PROJECT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

COMPANY	ABC & Co.	PROJECT	Project 3 Test
Date Of Incident	May 21, 2018	Time Of Incident	01:09 PM
Inspector	user@gmail.com		

# **QUESTIONS:**

## Question # 1. Safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)

#### satisfactory

Question # 2. Good housekeeping being maintained

na

Jjjkjkhjiwcfe Huwihfiweufjiwrcwe Ijninuih Kniin

Question # 3. Fall Protection in place where required

#### satisfactory

Question # 4. Confined Space procedures being followed

satisfactory

Question # 5. Trenching & excavation work being done safely

### satisfactory

Question # 6. Scaffolding safety procedures are being followed

# Answer : Unsatisfactory

Copyright @2018 Safety Compliance Company. All rights reserved. This document is intended as a safety tailgate meeting and does not contain all OSHA regulations. Please refer to OSHA and other state and federal agencies for further and current regulations. Not to be duplicated or distributed for use without the express written consent of Safety Compliance Company.