



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

COMPANY	ABC & Co.	PROJECT	Project 3 Test
Date Of Incident	June 03, 2018	Time Of Incident	06:04 PM
Inspector	user@gmail.com		

QUESTIONS:

Question # 1. OSHA permit is present

satisfactory

Question # 2. Is a protective system in place for the trench if 5' or deeper?

Answer : **Unsatisfactory**

- UNSATISFACTORY ITEM # 1

Unsatisfactory Note

Test

Unsatisfactory Photo

-

Recipient Name

Recipient Email