

followed

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| Company | ABC & Co. | Type of Inspection: | General Contractor Inspection | | |
|-----------------------------------------|----------------|---------------------|-------------------------------|--|--|
| Project | Project 3 Test | Date Of Incident | June 17, 2018 | | |
| Inspector Name | user@gmail.com | Time Of Incident | 12:43 AM | | |
| INSPECTION ITEMS | | | | | |
| INOI EGITON II EMO | | | | | |
| Item | | | Comment | | |
| Safety documentation available (Written | | | | | |

| Safety Programs, SDS, Tailgate Meetings) | Satisfactory | |
|-----------------------------------------------|----------------|--|
| Good housekeeping being maintained | Satisfactory | |
| Fall Protection in place where required | Satisfactory | |
| Confined Space procedures being followed | Satisfactory | |
| Trenching & excavation work being done safely | Satisfactory | |
| Scaffolding safety procedures are being | Unsatisfactory | |

UNSATISFACTORY ITEMS

Photo Corrective Action Comment Minni Nono