

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	ABC & Co.	Type of Inspection:	Roofing Inspection
Project	Project 3 Test	Date Of Incident	June 21, 2018
Inspector Name	user@gmail.com	Time Of Incident	02:40 PM

INSPECTION ITEMS

Item		Comment
Fall Protection	Satisfactory	
Trenching & excavation work being done safely	Satisfactory	
Trenching & excavation work being done safely	Satisfactory	
Scissor lifts / elevated platforms are being used safely	Satisfactory	
Tools & equipment are being used safely	Satisfactory	
Personal Protective Equipment is being worn as required	Satisfactory	
Are Safety Nets set up safely	Satisfactory	

Copyright @2018 Safety Compliance Company. All rights reserved. This document is intended as a safety tailgate meeting and does not contain all OSHA regulations. Please refer to OSHA and other state and federal agencies for further and current regulations. Not to be duplicated or distributed for use without the express written consent of Safety Compliance Company.