

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**

**ABC & Co.**

**PROJECT:**

**Project 3 Test**



**INSPECTION TYPE:**

**General Contractor Inspection**

**INSPECTOR :** TEST333@GMAIL.COM

**DATE :** JULY 05, 2018

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# INSPECTION ITEMS

Item	Comment
Is a protective system in place for the trench if 5' or deeper?	unsatisfactory
Safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	satisfactory
Good housekeeping being maintained	satisfactory
Confined Space procedures being followed	satisfactory
Trenching & excavation work being done safely	satisfactory
Trenching & excavation work being done safely	satisfactory
Trenching & excavation work being done safely	satisfactory
Scaffolding safety procedures are being followed	satisfactory
Scissor lifts / elevated platforms are being used safely	satisfactory
Tools & equipment are being used safely	satisfactory
Personal Protective Equipment is being worn as required	satisfactory
Are Safety Nets set up safely	satisfactory
Are spoils at least 2' back from the top of the trench?	satisfactory
Jhbhj hu jh	satisfactory

## CONTRACTOR VIEWED ON SITE

1 Jerry Disoza

2 Yersxx

## SUMMARY OF INSPECTION

Summary

## GENERAL PHOTOS AND COMMENTS

Photo	Comment
<p>Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs</p>	



Comment

## UNSATISFACTORY ITEMS

Photo	Comment	Corrective Action
	Note 1	
	Note 2	

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs