#### SAFETY INSPECTION REPORT

CONDUCTED FOR: ABC & Co.

> PROJECT: Project 3 Test



**INSPECTION TYPE:** General Contractor

**INSPECTOR** : ATAINDIGOICON@GMAIL.COM **DATE** : AUGUST 30, 2018

## **INSPECTION ITEMS**

Item		Comment
Safety Manual (GISO, 3202)	Satisfactory	
Tailgate Meetings (CSO, 1509)	Satisfactory	
SDS (CSO, 1594)	Satisfactory	
Daily Inspections (CS0, 1511)	Satisfactory	
Sub-Contractor Meetings (CSO, 3203)	Satisfactory	
Labor Law Posters (CSO, 3203)	Satisfactory	
Codes of Safe Practice / Emergency Posters (CSO, 3203)	Satisfactory	
Permits (CS0, 3203)	Satisfactory	
Fire Extinguisher (CSO, 1920-1938)	Satisfactory	     
Building Fire Extinguisher (CSO, 1926.150)	Satisfactory	
First Aid Kit (CSO, 1512)	Satisfactory	
First Aid / CPR Cert (CSO, 1512)	Satisfactory	
Restrooms / Washing Facilities (CSO, 1527)	Satisfactory	
Waste Containers (CSO, 1529)	Satisfactory	
Water Supply (CSO, 3395)	Satisfactory	     
Shade (CSO, 3395)	Na	
Power Tools (CSO, 3555)	Na	
Hand Tools (CSO, 1699)	Na	
Power Saws (CSO, 1680-1682)	Na	
Personal Protective Equipment (CSO, 1514)	Na	
Electrical Safety (CSO, 2299-2972, 1760)	Na	
Trenching & Excavation (CSO, 1539-1547)	Na	
Confined Space (CSO, 5157)	Na	
Fall Protection (CSO, 1669-1672)	Satisfactory	
Ladder Safety (CSO, 1675-1678)	Satisfactory	
Access / Egress (CSO, 1629-1631)	Satisfactory	

	Stairways / Ramps / Runways (CSO, 1623-1626)	Satisfactory	
	Heavy Equipment (CSO, 1590-1596)	Satisfactory	
	Crane / Rigging (CSO, 1610, 1619/50061)	Satisfactory	
r	Powder Actuated Tools (CSO 1684-1692)	Satisfactory	
P	Cylinder Storage (CSO 1739-1743)	Satisfactory	
	Floor, Roof, Wall Openings (CSO, 1626-1632)	Satisfactory	
	Railing (CSO, 1621)	Satisfactory	
	Material Storage (CSO, 1549)	Satisfactory	
	Impalement Hazards (CSO, 1712)	Satisfactory	
	Traffic Control (CSO, 1597-1599)	Satisfactory	
	Scissor Lifts / Boom Lifts (3646-3648)	Satisfactory	
	Powered Industrial Trucks (CSO, 3650-3669)	Satisfactory	
*	Scaffolding / Shoring (CSO, 1635.1-1655)	Satisfactory	
	Suspended Scaffolding (CSO, 1658-1667)	Satisfactory	
	Silica Exposure / Dust (CSO, 5155, 5128-1537)	Na	
	Hot Work (CSO, 6777)	Na	
*	Housekeeping (CSO, 1513)	Na	
	Roofing Operations (CSO, 1723-1731)	Na	
	Demolition (CSO, 1733)	Na	last na
1			

# **CONTRACTORS VIEWED ON SITE**

- 1 Testing Contractor
- 2 Jerry Disoza
- 3 Hourse
- 4 Yersxx
- 5 sjsjs
- 6 55555
- 7 sha

### SUMMARY OF INSPECTION

summary

### **GENERAL PHOTOS AND COMMENTS**

Photo	Comment
bh	image from cemra
N/A	sgsgss
N/A	hshshs
N/A	hshshs