



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	San Joaquin Valley Homes: Construction	<b>Type of Inspection:</b>	General Construction
<b>Project</b>	Greystone	<b>Date of Inspection</b>	March 24, 2021
<b>Inspector Name</b>	Connor Merrill	<b>Time of Inspection</b>	09:19 AM

## INSPECTION ITEMS

Item	Comment	Photo
is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory	-
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory	-
Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory	-
Are emergency and labor law postings in place?	Satisfactory	-
Is Personal Protective Equipment being worn as required?	Satisfactory	-
Are scaffolding safety procedures being followed?	Satisfactory	-
Are hand and power tools being used safely?	Satisfactory	-
Is good housekeeping being maintained?	Satisfactory	-
Is fall protection in place where required?	Satisfactory	-
Is trenching & excavation work being done safely?	Satisfactory	-
Are confined space safety procedures being followed?	Satisfactory	-
Are scissor lifts / elevated platforms being used safely?	N/A	-
Are boom lifts and other aerial devices being used safely?	N/A	-
Is heavy equipment being used safely?	Satisfactory	-

Are electrical items being used safely?	Satisfactory		-
Are roofing operations being performed safely?	Satisfactory		-
Is demolition work being done safely?	N/A		-
Are all other tasks being performed safely?	Satisfactory		-