



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

|                       |  |                            |   |
|-----------------------|--|----------------------------|---|
| <b>Company</b>        | San Joaquin Valley Homes: Construction | <b>Type of Inspection:</b> | San Joaquin Valley Homes Daily Inspection |
| <b>Project</b>        | Greystone                              | <b>Date of Inspection</b>  | April 13, 2021                            |
| <b>Inspector Name</b> | Connor Merrill                         | <b>Time of Inspection</b>  | 08:40 AM                                  |

## INSPECTION ITEMS

| Item   | Comment      | Photo |
|--|--------------|-------|
| is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? | Satisfactory | -     |
| Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)    | Satisfactory | -     |
| Is drinking water and shade set up sufficient for the amount of workers?               | Satisfactory | -     |
| Are emergency and labor law postings in place?   | Satisfactory | -     |
| Is Personal Protective Equipment being worn as required?                               | Satisfactory | -     |
| Are scaffolding safety procedures being followed?                                      | Satisfactory | -     |
| Are hand and power tools being used safely?  | Satisfactory | -     |
| Is good housekeeping being maintained?   | Satisfactory | -     |
| Is fall protection in place where required?  | Satisfactory | -     |
| Is trenching & excavation work being done safely?                                      | Satisfactory | -     |
| Are confined space safety procedures being followed?                                   | Satisfactory | -     |
| Are scissor lifts / elevated platforms being used safely?                              | N/A          | -     |
| Are boom lifts and other aerial devices being used safely?                             | N/A          | -     |
| Is heavy equipment being used safely?  | Satisfactory | -     |

|  |                |                               |   |
|--|----------------|-------------------------------|---|
| Are electrical items being used safely?        | Satisfactory   |                               | - |
| Are roofing operations being performed safely? | Satisfactory   |                               | - |
| Is demolition work being done safely?          | N/A            |                               | - |
| Are all other tasks being performed safely?    | Unsatisfactory | JR Concrete No caps on stakes | - |

## UNSATISFACTORY ITEMS

| Photo | Comment                       | Corrective Action |
|-------|-------------------------------|-------------------|
| -     | JR Concrete No Caps On Stakes |                   |