

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| Company | Semios | Type of Inspection: | Post Trip Trailer Inspection: Semios |
|----------------|------------------------|------------------------|--------------------------------------|
| Project | Trailer - 11 (4RM1836) | Date of Inspection | July 27, 2022 |
| Inspector Name | Macro Avala | Time of Inspection | 06:14 PM |

INSPECTION ITEMS

| Item | | Comment | Photo |
|-----------------------------------------------------------------------------------------------------------------|--------------|---------|----------------------------------------|
| Click "Satisfactory", take a photo of the license plate number or enter it in the comments section below. | Satisfactory | | - Entiformia Porm Prailer - 4RM1836 |
| Click "Satisfactory" and enter your Semios branch in the comments section below. | Satisfactory | turlock | - |
| Brakes: Are the brake connections in good condition? | Satisfactory | | - |
| Landing Gear: Is the landing gear in good condition? | Satisfactory | | - |
| Hitch: Is the hitch in good condition? | Satisfactory | | - |
| Doors: Are the doors in good condition? | Satisfactory | | - |
| Coupling: Is the coupling {king} pin in good condition? | Satisfactory | | - |
| Coupling: Are the coupling devices in good condition? | Satisfactory | | - |
| Brakes: Are the brakes in good condition? | Satisfactory | | - |
| All Lights: Are all lights working properly? | Satisfactory | | - |
| Reflectors: Are the reflectors working properly and is the reflective tape visible and in good condition? | Satisfactory | | - |
| Roof: Is the roof in good condition? | Satisfactory | | - |
| Suspension System: Is the suspension system working properly and in good condition? | Satisfactory | | - |

| Tarpaulin: Is the tarpaulin in good condition? | Satisfactory | - |
|-----------------------------------------------------------------------------------------|--------------|---|
| Tires: Are the tires in good condition? | Satisfactory | - |
| Wheels: Are the wheels and rims in good condition? | Satisfactory | - |
| Breakaway Cable: Is the breakaway cable in good condition? | Satisfactory | - |
| Side Rails: Are the side rails secure? | Satisfactory | - |
| Cargo: Is all cargo secure? | Satisfactory | - |
| Trailer Deck: Is the trailer deck in good condition? | Satisfactory | - |
| Is there anything else deficient? If so, please describe in the comments section below. | Satisfactory | - |
| If using tie down straps, are they fit for use? | Satisfactory | - |