

Roof: Is the roof in good condition?

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Semios	Type of Inspection:	Post Trip Trailer Inspection: Semios
Project	Trailer - 18 (4SR6403)	Date of Inspection	May 25, 2022
Inspector Name	Francisco Martinez	Time of Inspection	04:54 PM

	Comment	Photo				
Satisfactory		L.SR6403				
Satisfactory	Fresno	-				
Satisfactory		-				
Satisfactory		-				
Satisfactory		-				
Satisfactory		-				
Satisfactory		-				
Satisfactory		-				
Satisfactory		-				
Satisfactory		-				
Satisfactory		-				
	Satisfactory Satisfactory Satisfactory Satisfactory Satisfactory Satisfactory Satisfactory Satisfactory Satisfactory Satisfactory Satisfactory Satisfactory	SatisfactoryFresnoSatisfactoryFresnoSatisfactory				

Satisfactory

-

Suspension System: Is the suspension system working properly and in good condition?	Satisfactory	-
Tarpaulin: Is the tarpaulin in good condition?	Satisfactory	-
Tires: Are the tires in good condition?	Satisfactory	-
Wheels: Are the wheels and rims in good condition?	Satisfactory	-
Breakaway Cable: Is the breakaway cable in good condition?	Satisfactory	-
Side Rails: Are the side rails secure?	Satisfactory	-
Cargo: Is all cargo secure?	Satisfactory	-
Trailer Deck: Is the trailer deck in good condition?	Satisfactory	-
Is there anything else deficient? If so, please describe in the comments section below.	Satisfactory	-
If using tie down straps, are they fit for use?	Satisfactory	-