




# EQUIPMENT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

|                       |                        |                            |                                     |
|-----------------------|------------------------|----------------------------|-------------------------------------|
| <b>Company</b>        | Semios                 | <b>Type of Inspection:</b> | Pre Trip Trailer Inspection: Semios |
| <b>Project</b>        | Trailer - 18 (4SR6403) | <b>Date of Inspection</b>  | June 28, 2022                       |
| <b>Inspector Name</b> | Francisco Martinez     | <b>Time of Inspection</b>  | 05:06 AM                            |

## INSPECTION ITEMS

| Item  |              | Comment | Photo  |
|---|--------------|---------|--|
| Click "Satisfactory" and enter your Semios branch in the comments section below.                          | Satisfactory | Fresno  | -  |
| Click "Satisfactory", take a photo of the license plate number or enter it in the comments section below. | Satisfactory |         |  |
| Brakes: Are the brake connections in good condition?  | Satisfactory |         | -  |
| Landing Gear: Is the landing gear in good condition?  | Satisfactory |         | -  |
| Hitch: Is the hitch in good condition?  | Satisfactory |         | -  |
| Doors: Are the doors in good condition?   | Satisfactory |         | -  |
| Coupling: Is the coupling {king} pin in good condition?   | Satisfactory |         | -  |
| Coupling: Are the coupling devices in good condition?   | Satisfactory |         | -  |
| Brakes: Are the brakes in good condition?   | Satisfactory |         | -  |
| All Lights: Are all lights working properly?  | Satisfactory |         | -  |
| Reflectors: Are the reflectors working properly and is the reflective tape visible and in good condition? | Satisfactory |         | -  |
| Roof: Is the roof in good condition?  | Satisfactory |         | -  |

|   |              |  |   |
|---|--------------|--|---|
| Suspension System: Is the suspension system working properly and in good condition?     | Satisfactory |  | - |
| Tarpaulin: Is the tarpaulin in good condition?  | Satisfactory |  | - |
| Tires: Are the tires in good condition?   | Satisfactory |  | - |
| Wheels: Are the wheels and rims in good condition?                                      | Satisfactory |  | - |
| Breakaway Cable: Is the breakaway cable in good condition?                              | Satisfactory |  | - |
| Side Rails: Are the side rails secure?  | Satisfactory |  | - |
| Cargo: Is all cargo secure?   | Satisfactory |  | - |
| Trailer Deck: Is the trailer deck in good condition?                                    | Satisfactory |  | - |
| Is there anything else deficient? If so, please describe in the comments section below. | Satisfactory |  | - |
| If using tie down straps, are they fit for use?   | Satisfactory |  | - |