

## **EQUIPMENT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| Company        | Semios                 | Type of<br>Inspection: | Post Trip Trailer Inspection: Semios |
|----------------|------------------------|------------------------|--------------------------------------|
| Project        | Trailer - 18 (4SR6403) | Date of Inspection     | July 18, 2022                        |
| Inspector Name | Francisco Martinez     | Time of Inspection     | 02:21 PM                             |

## **INSPECTION ITEMS**

| Item  |              | Comment | Photo    |
|---|--------------|---------|----------|
| Click "Satisfactory", take a photo of the license plate number or enter it in the comments section below. | Satisfactory |         | 4.SR6403 |
| Click "Satisfactory" and enter your Semios branch in the comments section below.                          | Satisfactory | Fresno  | -        |
| Brakes: Are the brake connections in good condition?  | Satisfactory |         | -        |
| Landing Gear: Is the landing gear in good condition?  | Satisfactory |         | -        |
| Hitch: Is the hitch in good condition?  | Satisfactory |         | -        |
| Doors: Are the doors in good condition?   | Satisfactory |         | -        |
| Coupling: Is the coupling {king} pin in good condition?   | Satisfactory |         | -        |
| Coupling: Are the coupling devices in good condition?   | Satisfactory |         | -        |
| Brakes: Are the brakes in good condition?   | Satisfactory |         | -        |
| All Lights: Are all lights working properly?  | Satisfactory |         | -        |
| Reflectors: Are the reflectors working properly and is the reflective tape visible and in good condition? | Satisfactory |         | -        |
| Roof: Is the roof in good condition?  | Satisfactory |         | -        |

| Suspension System: Is the suspension system working properly and in good condition?     | Satisfactory | - |
|---|--------------|---|
| Tarpaulin: Is the tarpaulin in good condition?  | Satisfactory | - |
| Tires: Are the tires in good condition?   | Satisfactory | - |
| Wheels: Are the wheels and rims in good condition?                                      | Satisfactory | - |
| Breakaway Cable: Is the breakaway cable in good condition?                              | Satisfactory | - |
| Side Rails: Are the side rails secure?  | Satisfactory | - |
| Cargo: Is all cargo secure?   | Satisfactory | - |
| Trailer Deck: Is the trailer deck in good condition?                                    | Satisfactory | - |
| Is there anything else deficient? If so, please describe in the comments section below. | Satisfactory | • |
| If using tie down straps, are they fit for use?   | Satisfactory | - |