

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Semios	Type of Inspection:	Pre Trip Trailer Inspection: Semios
Project	Trailer - 19 (4SA7522)	Date of Inspection	December 15, 2021
Inspector Name	Francisco Martinez	Time of Inspection	06:07 AM

INSPECTION ITEMS Item Comment Photo Click "Satisfactory" and enter your Semios branch in the comments section below. Satisfactory Fresno Click "Satisfactory", take a photo of the license plate number or enter it in the Satisfactory comments section below. Brakes: Are the brake connections in Satisfactory good condition? Landing Gear: Is the landing gear in good Satisfactory _ condition? Hitch: Is the hitch in good condition? Satisfactory -Doors: Are the doors in good condition? Satisfactory -Coupling: Is the coupling {king} pin in Satisfactory good condition? Coupling: Are the coupling devices in Satisfactory _ good condition? Brakes: Are the brakes in good condition? Satisfactory All Lights: Are all lights working properly? Satisfactory _ Reflectors: Are the reflectors working properly and is the reflective tape visible Satisfactory and in good condition? Roof: Is the roof in good condition? Satisfactory -

Suspension System: Is the suspension system working properly and in good condition?	Satisfactory	-
Tarpaulin: Is the tarpaulin in good condition?	Satisfactory	-
Tires: Are the tires in good condition?	Satisfactory	-
Wheels: Are the wheels and rims in good condition?	Satisfactory	-
Breakaway Cable: Is the breakaway cable in good condition?	Satisfactory	-
Side Rails: Are the side rails secure?	Satisfactory	-
Cargo: Is all cargo secure?	Satisfactory	-
Trailer Deck: Is the trailer deck in good condition?	Satisfactory	-
Is there anything else deficient? If so, please describe in the comments section below.	Satisfactory	-
If using tie down straps, are they fit for use?	Satisfactory	-