

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Semios	Type of Inspection:	Post Trip Trailer Inspection: Semios
Project	Trailer - F04	Date of Inspection	October 29, 2020
Inspector Name	Heriberto Romero	Time of Inspection	03:36 PM

INSPECTION ITEMS						
Item		Comment	Photo			
Click "Satisfactory", take a photo of the license plate number or enter it in the comments section below.	Satisfactory		California Press Press LRD7213			
Click "Satisfactory" and enter your Semios branch in the comments section below.	Satisfactory		-			
Brakes: Are the brake connections in good condition?	Satisfactory		-			
Landing Gear: Is the landing gear in good condition?	Satisfactory		-			
Hitch: Is the hitch in good condition?	Satisfactory		-			
Doors: Are the doors in good condition?	Satisfactory		-			
Coupling: Is the coupling {king} pin in good condition?	Satisfactory		-			
Coupling: Are the coupling devices in good condition?	Satisfactory		-			
Brakes: Are the brakes in good condition?	Satisfactory		-			
All Lights: Are all lights working properly?	Satisfactory		-			
Reflectors: Are the reflectors working properly and is the reflective tape visible and in good condition?	Satisfactory		-			
Roof: Is the roof in good condition?	Satisfactory		-			

Suspension System: Is the suspension system working properly and in good condition?	Satisfactory	-
Tarpaulin: Is the tarpaulin in good condition?	Satisfactory	-
Tires: Are the tires in good condition?	Satisfactory	-
Wheels: Are the wheels and rims in good condition?	Satisfactory	-
Breakaway Cable: Is the breakaway cable in good condition?	Satisfactory	-
Side Rails: Are the side rails secure?	Satisfactory	-
Cargo: Is all cargo secure?	Satisfactory	-
Trailer Deck: Is the trailer deck in good condition?	Satisfactory	-
Is there anything else deficient? If so, please describe in the comments section below.	Satisfactory	-