

## **EQUIPMENT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Semios	Type of Inspection:	Pre Trip Trailer Inspection: Semios
Project	Trailer - F04	Date of Inspection	March 15, 2021
Inspector Name	Luis Leon	Time of Inspection	04:50 PM

## **INSPECTION ITEMS** Item Comment Photo Click "Satisfactory" and enter your Semios branch in the comments section below. Satisfactory Fresno Click "Satisfactory", take a photo of the license plate number or enter it in the Satisfactory comments section below. Brakes: Are the brake connections in Satisfactory good condition? Landing Gear: Is the landing gear in good Satisfactory condition? Hitch: Is the hitch in good condition? Satisfactory \_ Doors: Are the doors in good condition? N/A \_ Coupling: Is the coupling {king} pin in Satisfactory \_ good condition? Coupling: Are the coupling devices in Satisfactory \_ good condition? Brakes: Are the brakes in good condition? Satisfactory All Lights: Are all lights working properly? Satisfactory \_ Reflectors: Are the reflectors working properly and is the reflective tape visible Satisfactory \_ and in good condition? Roof: Is the roof in good condition? N/A -Suspension System: Is the suspension system working properly and in good Satisfactory condition?

Tarpaulin: Is the tarpaulin in good condition?	Satisfactory	-
Tires: Are the tires in good condition?	Satisfactory	-
Wheels: Are the wheels and rims in good condition?	Satisfactory	-
Breakaway Cable: Is the breakaway cable in good condition?	Satisfactory	-
Side Rails: Are the side rails secure?	Satisfactory	-
Cargo: Is all cargo secure?	Satisfactory	-
Trailer Deck: Is the trailer deck in good condition?	Satisfactory	-
Is there anything else deficient? If so, please describe in the comments section below.	Satisfactory	-