EQUIPMENT INSPECTION

Generated by Safety Compliance App **www.safetycompliance.com** | **www.safetycomplianceapp.com**

Company	Semios	**Type of Inspection:**	Pre Trip Trailer Inspection: Semios
Project	Trailer - F05	**Date of Inspection**	February 08, 2021
Inspector Name	Matthew Howard	**Time of Inspection**	07:40 AM

INSPECTION ITEMS

Item		Comment	Photo
Click "Satisfactory" and enter your Semios branch in the comments section below.	Satisfactory	fresno	-
Click "Satisfactory", take a photo of the license plate number or enter it in the comments section below.	Satisfactory	4sa7522	-
Brakes: Are the brake connections in good condition?	Satisfactory		-
Landing Gear: Is the landing gear in good condition?	Satisfactory		-
Hitch: Is the hitch in good condition?	Satisfactory		-
Doors: Are the doors in good condition?	Satisfactory		-
Coupling: Is the coupling {king} pin in good condition?	Satisfactory		-
Coupling: Are the coupling devices in good condition?	Satisfactory		-
Brakes: Are the brakes in good condition?	Satisfactory		-
All Lights: Are all lights working properly?	Unsatisfactory	back left light falling off	-

UNSATISFACTORY ITEMS

Photo	Comment	Corrective Action